

egzumer /
uv-k5-firmware-custom

<> Code

Issues 41

Pull requests 5

Discussions

Actions

Wiki

Differences from QS stock firmware

[Jump to bottom](#)

egzumer edited this page on Nov 8, 2023 · 1 revision

Not all original features are available in this firmware.

Because the size of the firmware is limited (60kB), not all functionalities may be available in the firmware. That is why a choice was made so that other functionality could be realized in the radio. The menu has also been adjusted as a result. See [Menu](#) for a current description.

The most important differences compared to the original firmware are:

```
ENABLE_AIRCOPY := 0
```

```
ENABLE_NOAA := 0
```

```
ENABLE_VOICE := 0
```

```
ENABLE_ALARM := 0
```

```
ENABLE_TX1750 := 0
```

```
ENABLE_PWRON_PASSWORD := 0
```

If you want to change something here, read the **README.md** under [User customization](#).

▼ Pages 9

Find a page...

▶ [Home](#)

▶ [Button functions](#)

▶ [Development notes](#)

[Differences from QS stock firmware](#)

▶ [Flashing the firmware](#)

▶ [FM broadcast radio receiver](#)

▶ [Menu](#)

▶ [Radio operation](#)

▶ [Spectrum analyzer](#)

Clone this wiki locally

https://github.com/egzumer/uv-k5-firmware-custom/wiki.git

