

Introduction to UV-K5 HF 0.5 (Fullband receive version)

April 07, 2024

Introduction to
UV-K5 HF 0.5
(Fullband receive
version)

SHARE



This is an introduction to
UV-K5 HF full-band
reception firmware 0.4HF
using SI4732-A10.

This version is released
separately from the
existing UV-K5 CEC
firmware version. because
space is needed to store a
large PATCH file to use
SI4732-A10's SSB.

This article only describes
the features newly added
in Version 0.5.

Please check the links
below for full features.

How to modify your

hardware

<http://>

[www.hamskey.com/2024/](http://www.hamskey.com/2024/02/uv-k5s-hf-full-band-reception-lsb-usb.html)

[02/uv-k5s-hf-full-band-](http://www.hamskey.com/2024/02/uv-k5s-hf-full-band-reception-lsb-usb.html)

[reception-lsb-usb.html](http://www.hamskey.com/2024/02/uv-k5s-hf-full-band-reception-lsb-usb.html)

Version 0.3HF (Most

feature descriptions are

provided)

<http://>

[www.hamskey.com/2024/](http://www.hamskey.com/2024/02/introduction-to-uv-k5-hf-fullband.html)

[02/introduction-to-uv-](http://www.hamskey.com/2024/02/introduction-to-uv-k5-hf-fullband.html)

[k5-hf-fullband.html](http://www.hamskey.com/2024/02/introduction-to-uv-k5-hf-fullband.html)

Version 0.41HF

(Description of Band plan

function and Dual RX

function)

<http://>

[www.hamskey.com/2024/](http://www.hamskey.com/2024/03/introduction-to-uv-k5-hf-fullband.html)

[03/introduction-to-uv-](http://www.hamskey.com/2024/03/introduction-to-uv-k5-hf-fullband.html)

[k5-hf-fullband.html](http://www.hamskey.com/2024/03/introduction-to-uv-k5-hf-fullband.html)

1.Shortcut key description

After several version

changes, the shortcut key was confirmed.

1.1 Frequency fine tuning (Under 1Khz)

Number keys 1 and 4 can be used to change the frequency in 10Hz increments.

Although it is a BFO adjustment, the BFO is reflected in reverse, so it has the same effect as changing the frequency below 1Khz in SSB mode.



1.2 Change frequency step

When you press the
STAR(*) button, the step
changes.
Step is underlined at the
top of the screen and
below the main frequency.



(100KHz Step)

In version 0.5, steps
500KHz, 50KHz, and 5KHz
were added.



(50KHz Step)

1.3 Band Plan

When you press number

key 0, Band Plan is displayed. Please check the link below for Band Plan related functions.

Version 0.41HF

(Description of Band plan function and Dual RX function)

[http://
www.hamskey.com/2024/
03/introduction-to-uv-
k5-hf-fullband.html](http://www.hamskey.com/2024/03/introduction-to-uv-k5-hf-fullband.html)

1.4 Mode Change

Pressing the 'F' key changes the mode.

Short press 'F' to change to AM<->FM or LSB->USB->CW.

Press and hold 'F' to change to AMorFM <-> SSB or CW mode.

2.Direct Input Frequency

If you press any number

except the above shortcut key, direct frequency input mode will be activated.



Enter the desired frequency.

When you press the Exit button, the direct frequency input mode is canceled.



When all frequencies are input, the band appropriate for the frequency is automatically set.



3. Changed features


- Frequency step changes from large to small increments.

(1Mhz -> 500Khz -> 100Khz -> 50Khz -> 10Khz -> 5Khz -> 1Khz)

- When you select a band from the Band Plan menu, the mode appropriate for that band is automatically set.

- Unused and unnecessary menus have been removed. (Main VFO Mode, not HF Receive mode) : U.INFO, Key.LCK (If you press the F key for a

long time in main vfo
mode, Lock will be
activated or deactivated, so
it has been removed from
the menu)



4.Download

[https://github.com/
phdlee/uvk5cec/releases/
tag/v_01HF](https://github.com/phdlee/uvk5cec/releases/tag/v_01HF)

 CEC_02.HF.bin	
 CEC_02.HF.packed.bin	
 CEC_03.HF.bin	
 CEC_03.HF.packed.bin	
 CEC_04.HF.packed.bin	Version 0.5 HF
 CEC_041.HF.packed.bin	
 CEC_05.HF.packed.bin	

SHARE

Comments



on4bgc

• April 8, 2024 at 12:52 AM

Great job! I like it ;-)



KD8CEC

• April 8, 2024 at
12:53 AM

tnx

REPLY



Mikhail Yudin

• April 8, 2024 at 3:24 AM

Could you publish version
with 240 MHz filter
switch bound instead of
280 MHz?

[https://github.com/
phdlee/uvk5cec/
blob/4dd5de38bf7e94e60
066fe5c15a24b3be97312cf
/driver/bk4819.c#L829](https://github.com/phdlee/uvk5cec/blob/4dd5de38bf7e94e60066fe5c15a24b3be97312cf/driver/bk4819.c#L829)

REPLY



Buddym

• April 8, 2024 at 5:42 PM

Just brilliant, nice work.
REPLY
Thanks



German

• April 9, 2024 at 6:25 PM

Great job, I'm really enjoying it. You can support 128k eeprom (M24M01 - 999 channels) and CHIRP software. Thanks. 73.



Unknown

• June 22, 2024 at 5:49 PM

I also ask you to add a version with 24c512 or higher, thanks)

REPLY



Alfred

• April 10, 2024 at 3:49 AM

Hello
The speaker is very close to the electronic components of the board. How the BFO stability problem was solved. The frequency changes when you move your hand closer.

REPLY



K14

• April 10, 2024 at 7:24 AM

+1 to chirp module and bigger eeprom support (in my case I use a 24C512, but eventually I'll upgrade). Fantastic work! 73 de IU3POA

REPLY



Unknown

· April 10, 2024 at 6:10 PM

DSB TX Mode like IJV)

REPLY



SQ6OS

· April 11, 2024 at 1:58 AM

BFO stability problem
solution ;D

<https://ibb.co/HBj276m>



Alfred

· April 11, 2024 at
4:58 AM

Now how to
enclose it in a
housing with a
speaker and
keyboard?

REPLY



EarwiggerM7

· April 15, 2024 at 6:56 AM

This comment has been
removed by the author.

REPLY



UD3SBV

· April 16, 2024 at 8:41 AM

Hello! Great idea with
si4732. SSB lacks gain.
Make register control
Automatic gain control
max gain

REPLY



klaute - Kai Lauterbach -
DO4KLA

· April 18, 2024 at 9:11 AM

I have started to analyze
the 0.5 CEC firmware and
try to write a chirp

REPLY

plugin. It's not working
yet: [https://
git.okoyono.de/klaute/
uvk5-cec-chirp-driver](https://git.okoyono.de/klaute/uvk5-cec-chirp-driver)



Alfred

· April 18, 2024 at
2:34 PM

This comment
has been
removed by the
author.



Alfred

· April 19, 2024 at
8:07 AM

This comment
has been
removed by the
author.



Alfred

· April 19, 2024 at
8:08 AM

This comment
has been
removed by the
author.



Alfred

· April 19, 2024 at
1:50 PM

This comment
has been
removed by the
author.

Anonymous

• April 29, 2024 at
4:21 AM

This comment
has been
removed by the
author.

Anonymous

• April 29, 2024 at
4:23 AM

Thanks Kai, that
is what i missing!
Also a 999
channel version
for eeprom
upgrades ;)



**klaute - Kai Lauterbach -
DO4KLA**

• April 19, 2024 at 11:58 PM

Please do not post any
errors to this blog, i will
not read them anyways
Alfred. My chirp module
is in development and
does not belong to the
CEC firmware. My github
repository has a issue-
section. If you really need
to let me know that you
have problems using my
software - which is not
ready to use yet - dot it in
my repository.

REPLY



Frankie V

• April 21, 2024 at 10:17 AM

Thanks for the mod, great
work! I have installed it,
the chip resets, but I'm
unable to tune any
frequency, pressing the
side buttons exit HF

REPLY

mode and bring me back to normal mode. Any idea what I've done wrong here?



Eugen

• April 30, 2024 at 1:55 PM

Hello!

When you turn on the radio, the si4732 chip is immediately supplied with power. When you hold down the "0" key, short wave reception is turned on; the supply voltage is also present on the chip. When exiting this mode, power supply voltage is not supplied to the chip.

Is it possible to prevent the chip from being supplied with power when the radio is turned on?

REPLY



JustFun2405

• May 10, 2024 at 7:21 PM

This comment has been removed by the author.

REPLY



JustFun2405

• May 10, 2024 at 7:25 PM

I have the problem that when I keep pressing the 0 button, the display just says Wait. and then the device freezes.

Everything is installed properly and tested for continuity.

I installed the Lusya modification module including si4732 chip and

REPLY

crystal oscillator parts for
Quan Sheng UV-K5
[https://
drive.google.com/file/
d/1PsEqBSLvNJU0jdlPTXe
ifYdeqDQVOTrX/view?
usp=sharing](https://drive.google.com/file/d/1PsEqBSLvNJU0jdlPTXeifYdeqDQVOTrX/view?usp=sharing)



Tirwal

• May 15, 2024 at
1:43 AM

Just al the left of
the bottom of the
connection to
BK1080 must be a
1k resistor that is
missing. The
resistor connects
with pin8.



JustFun2405

• May 15, 2024 at
3:00 AM

@Tirwal ich liebe
dich... Genau das
war das Problem,
habe ihn jetzt aus
einem anderen
Gerät ausgebaut
und dort
eingesetzt.... Es
funktioniert
endlich. Du bist
meine Rettung.....
Was genau ist das
für ein
Widerstand,
damit ich ihn in
das Ersatzgerät
wieder einbauen
kann.....



Tirwal

• May 17, 2024 at
3:03 AM

It's a simple
1kohm resistor in

serial communications lines of the chip. I lost one of mine during BK1080 removal. Then I broke the other during repairing the first. I've almost got crazy. When I studied electrical scheme, I found where could be the problem. It's there or in RST pin. I discarded RST, then I traced the problem to this lines. Another problem is a fail connections between lines on the main board of BK1080 and the new circuit, because copper lines don't end in the border. There is a thin line of plastic that avoid good connections with solder. I use a small piece of copper hair cable to better the connections.



Howcome

• November 29,
2024 at 5:47 AM

I have install the mod-board v2.0 and I too have that WAIT problem. I have been reading all

comments
regarding this
issue. Just two
questions:
1) what is a
BK1080?
2) is there a
schematic of this
board and where
to place the
resistor?

Any help would
be appreciated.



Howcome

• November 30,
2024 at 3:55 AM

I have found info
on the 1080. It is
the chip that has
to be removed to
solder on the
mod board,
right?? So, do i
need to place a 1K
resistor in the
SCLK connection
(pin 8) from the
PCB to the mod
board?



JustFun2405

• May 12, 2024 at 1:10 PM

Ich habe auch alles
gemessen alle Kontakte
vOm Gerät zum Board
ect. Ich suche seit Tagen
nach Lösungen, aber
nichts gefunden oder
hilft. Ich glaube langsam
das es an Si4732 liegt 🤔

REPLY



REPLY
DS5WIS

• May 14, 2024 at 5:58 AM

This comment has been removed by the author.



DS5WIS

• May 14, 2024 at 6:00 AM

It stops at the "Wait" screen and cannot proceed any further. What is the solution?



JustFun2405

• May 14, 2024 at 6:07 AM

Ich habe noch keine Lösung gefunden 😞

Anonymous

• May 14, 2024 at 6:14 AM

Flash IJV an use the Reset All function in the Service Menu. Flash CEC_05 again and try it.



JustFun2405

• May 14, 2024 at 6:26 AM

Funktioniert auch nicht



DS5WIS

• May 14, 2024 at 7:07 AM

This is my close friend's equipment. It hasn't been resolved yet.

REPLY

Anonymous

• May 14, 2024 at
9:26 AM

Ok, but please tell
me does IJV
work?



JustFun2405

• May 14, 2024 at
9:44 AM

Die IJV Firmware
läuft..



JustFun2405

• May 14, 2024 at
9:55 AM

Nein, weder der
VFO noch All
Reset der IJV hat
geholpen. Ich
habe auch jede
Firmware Version
versucht... von 0.1
- 0.51



WCATFN

• February 4, 2025
at 3:24 PM

I had this - it
turned out that
the large round
ground
connection,
whilst filled with
solder, it was not
making an
electrical contact
with the
motherboard. I
removed the
daughter-board
and found a layer
of hardened flux
but no solder on
the main board.
I gently scored

the metal on the main board and used a much hotter soldering bit to 'tin' the metal, then refitted the daughter-board - worked after that.



Mananan

• May 14, 2024 at 1:18 PM

Can anyone let me know what software needed to read and write memories
Struggling at the moment with 0.41

REPLY



Tirwal

• May 17, 2024 at 3:35 AM

Ticking sound makes almost impossible to hear something in low bands. Could be possible a key stroke that stops Smeter or other things to reduce ticking sound on demand?. When push 0 key to access bands ticking sound reduces a lot... I propose 0 long stroke that stops or starts Smeter... In high bands doesn't bothered...

REPLY



cowboy

• May 24, 2024 at 7:40 AM

poderia adicionar o analisador de espectro igual ao egzumer...



JustFun2405

• May 24, 2024 at 10:20 AM

REPLY

That would be an
option, its
Spectrum
Analyser + Search
function



DJ7FG - Frank -

• May 25, 2024 at 6:29 AM

Great Firmware! I love it!!
Quick Question: Which
CPS is recommended to
change e. g. Memory
Channels? Is the original
CPS OK ("Portable radio
customer programming
software V 1.0.38) ?

REPLY



JustFun2405

• May 25, 2024 at 9:16 AM

Chirp funktioniert mit
dem Egzumer Modul sehr
gut.
Dran denken das Du
durch die cec Firmware
"nur" 145 Speicherplätze
hast



DJ7FG - Frank -

• May 25, 2024 at
2:20 PM

Besten Dank!
Werde ich gleich
mal mit der
Egzumer py
ausprobieren und
auch auf die
Speicherplätze
achten.

REPLY



Tirwal

• June 5, 2024 at 12:15 PM

REPLY made a mod of Chirp

driver to work with this firmware. Not all configs work, but is possible to download and upload memories and most of the configs. Also, it is possible to change initial freq of HF radio. Feel free to probe it. Link:
https://drive.google.com/file/d/1k6GkLhJKPqiCO7pOwezZnIHRdOwuTI3G/view?usp=drive_link



IceMan

• June 9, 2024 at 3:18 PM

Is it possible to add compatibility to the M24M02-DRMN6TP EEPROM ?

This eeprom would give the one feature that is missing now, 11.000+ memory channels.

Have already installed it and waiting to test..

REPLY



any

• June 12, 2024 at 5:02 PM

First and foremost I want to thank you for a great job! Your interface is probably the best among modifications for UV-K5 for HF reception. And there is a big request - make a small step 50 or 100Hz (now you have it 10 Hz), or maybe even to be able to adjust through the menu, for example 5-10-50-100 Hz. 10 Hz is very slow and uncomfortable.

REPLY



hicham

• July 1, 2024 at 9:48 AM

Drive-4Less.com Location de voiture Aéroport De fès A des Offres abordables. Réservez votre véhicule en ligne facilement et profitez d'un service client exceptionnel. Découvrez notre large gamme de véhicules disponibles pour répondre à tous vos besoins de transport lors de votre séjour à Fès. Pour plus d'informations et pour réserver, visitez notre site web Drive-4Less.com

location voiture fes
,location voiture à
fes,location voiture fes
aéroport,location voiture
à fès,location voiture
aéroport fes,location
voiture maroc fes

[https://](https://www.drive-4less.com)

REPLY

www.drive-4less.com



virona

• July 1, 2024 at 3:24 PM

Table games for families unite everybody, cultivating tomfoolery and holding through drawing in exercises. From exemplary prepackaged games to imaginative new difficulties, they engage all ages. With choices like Wished For, families can make vital minutes loaded up with giggling and cordial contests. [Table Games for Families](#)

REPLY



W7STF

• July 4, 2024 at 5:28 AM

Could someone advise us on what STMicroelectronics serial EEPROMs are compatible with the UV-K5 hardware? The firmware is pretty big, and I imagine the 512Kbit, 1Mbit or 2Mbit versions will need to replace what is in the radio. What model/speed/size are compatible? And, can the swap of the EEPROM be done and still allow for downloading (i.e. is the bootloader in the processor)? Thanks.

REPLY



RW4CMG

• July 12, 2024 at 1:07 AM

The firmware is interesting, thanks.

REPLY However, there are 2

drawbacks:

The main one is very low gain in SSB mode;

Minor - in AM mode the bandwidth is not adjusted. I really hope that someday this will be fixed. It's better to let the uv-k5 hiss like the ATS-100 than barely whisper, like now.



Electricleel

• July 24, 2024 at 1:50 PM

Using this firmware in the 0.51hf version. Everything works great but just a minor annoyance is that in the FM broadcast band the stations sound as if the signal is overloaded.

My mod board is the version 2.5 which has a completely separate antenna which feeds the am input of the si4732. The fm input of the si4731 is via the original unmodified Quansheng antenna circuit. What's going on with this? The si4732 should be able to provide a clean broadcast signal just as the original 8pin Quansheng fm broadcast chip did .

Is it limited by software or is it a hardware issue?

On research I've discovered that commercial fm broadcast stations sound overloaded if listened to in WFM rather than BFM (broadcast FM).

Does CEC hf firmware not support BFM? or am I

REPLY barking up the wrong

tree?



RW4CMG

• July 25, 2024 at
5:15 AM

The reason for your problem lies in the very large difference in volume in different modes of operation of the si4732 with this firmware. In order to make the SSB sound loud enough, the Chinese added an operational amplifier to the modification board. In the SSB mode, this amplifier eliminates the problem, but in the rest (AM/FM) it creates a new one (overloading the switch of the UV-K5 receivers). Now that the Chinese have produced such a variety of boards with stupid “crutches”, in order to correct the whole variety of “crooked solutions”, the author of the firmware needs to release at least 2 versions of corrections. One for those who have a modification board without an

op-amp and
another for those
who have a board
with an amplifier
:)



EA3GCV

• August 20, 2024 at
3:12 AM

Thank you for the
explanation. I also
experience this
issue. I hope
author will fix this
soon! Best 73



Electriceel

• July 30, 2024 at 2:33 PM

This comment has been
removed by the author.

REPLY



RW4CMG

• August 4, 2024 at 10:15 PM

The author of the
firmware doubted that
anyone would use his
brainchild on long waves.
I demonstrate how his
mod works on LW and at
the same time ask to
make a firmware update
containing a tuning
resolution of 9 kHz. And
of course with a gain
correction in SSB mode
[https://
youtu.be/0DgHd3KiCvc?
t=51](https://youtu.be/0DgHd3KiCvc?t=51)

REPLY



EA3GCV

• August 20, 2024 at 3:11 AM

REPLY

First of all thank you to

the author for such a great firmware! I'm experiencing a bug after upgrading to this firmware: PTT from handsets is not working anymore. I have tried 4 different handsets and all work well with unmodified K5 units but not after PCB v2.5 + CEC 0.51 firmware. So I guess it's a firmware issue. I will highly appreciate if author could release a new firmware version fixing all reported bugs. TNX and 73!



Andrei

• August 30, 2024 at 2:14 PM

Thanks a lot for the firmware. Is it possible to add 0.1 kHz (100 Hz) tuning step for SSB mode?

REPLY



Luna Azul Bridal

• September 18, 2024 at 10:36 AM

Luna Azul Bridal Gown Preservation Our specific preservation methods keep up with the texture and specifying of your gown, saving it in flawless condition for people in the future to appreciate.
[gown preservation](#)

REPLY



Wished For

• September 19, 2024 at 9:22 AM

Through associate
REPLY marketing, selling Wished

For products turns into an effortless method for generating income. By recommending their top-selling things, you can develop your crowd and appreciate consistent commission earnings.

[affiliate marketing selling product](#)



Adams

• October 9, 2024 at 9:27 AM

Find lovable baby girl bodysuits in the UK at Neil And Roo, where solace meets style for your little one. Our assortment highlights charming plans and delicate textures, ideal for keeping your baby girl comfortable and popular all day. [baby girl bodysuits in uk](#)

REPLY



Adams

• October 9, 2024 at 3:12 PM

Drip Infinity Men Bomber Jacket gets smooth style together with comfort, ideal for any season. Raise your wardrobe with an eternal piece planned for the state of the art man.

[Men Bomber Jacket](#)

REPLY



Adams

• October 17, 2024 at 5:44 PM

Open your business' greatest limit with Digital Meta Squad, your trusted in digital advertising

REPLY

advisor. Our lord bunch

addresses impressive
expert in making tweaked
techniques that raise your
online presence and drive
critical responsibility
with your vested party.
**digital marketing
solutions**



g2pa

• October 26, 2024 at
8:57 PM

I have just upgraded one of my UV-5R Plus radios to use the HF board, installed the 0.51HF firmware and have now got a small issue. Everything on HF seems to work but will test more tomorrow, on the normal V/U frequencies, again all seems fine, until I look at memories. Now I know a few people have posted CHIRP modules, but I can't get them to work, I found one that kicks an error saying a /tmp/ file is missing, and the other only shows 145 memories in CHIRP although the radio still has all 199? In the past for CEC I have used uvk5_IJV_v2.9R4_JH11.py with no issues, but now I have one. On memories that have a repeater offset + or -, although they show in CHIRP, the offset direction doesn't get to the radio. I have tried with all available CHIRP modules that sort of work, but none show the offset. So, the only **REPLY** on I have found so

far is go into the radio settings on the required channel, the offset frequency is still there but you have to add the offset direction + or - in menu 10, then go to menu 17 and re-save the memory, then is sticks, but if you save in CHIRP to edit something and re-push to the radio the changes do seem to stick. But as I have around 100 of my memories with a repeater offset, this is a real pain. Has anyone else had this issue and if so, did you find a solution for it? Any help gratefully received.



Dan W5DMH

• October 31, 2024 at 2:57 AM

Using version 0.51HF with a board and absolutely loving it! What a great upgrade! Any chance of seeing a built in CW decoder in the future?

REPLY



Mister Miyagi 91

• November 3, 2024 at 4:24 PM

I love their firmware. 😊

but unfortunately I can't find a Chirp module.

and soon I will install a 24M02RD EEPROM to have 1000 channels, I think CEC 0.51 HF doesn't support that. 😊

REPLY



Spiff

• December 16, 2024 at 6:01 AM

Is there still a way to reset the radio from within the menu? I wanted to do a "clean" update after flashing the firmware (0.51), but I can't find a reset menu like there is in the stock firmware menu?



WCATFN

• February 4, 2025 at 3:33 PM

I downgraded to the stock firmware, did the reset and then re-flashed CEC again, however now I can't get chirp to write memories...

REPLY



stevec5000

• December 25, 2024 at 4:45 PM

Where can I find a schematic of the little add on module that was installed in the radio?

REPLY



Unknown

• January 15, 2025 at 5:50 AM

I've been visiting this site for quite some time now, and the content has never disappointed. It's consistently excellent and informative. **Personal Trainer**

REPLY



Laikeen

• February 23, 2025 at 12:21 AM

Hello,
I've made all modifications and work with CEC0,51HF firmware.
It's not possible to program UV-K5 with CHIRP Software. Is there any other solutions?
I work with iMac Pro.
Thanks for your help
Best 73 from F5HUP

REPLY



Jim

• March 4, 2025 at 5:32 PM

I have a UV-k5(8) with the v5 mod board installed. I want to flash the 0.51 firmware. can I use the tool available on the Quansheng site to load the CEC bib file?



Jim

• March 4, 2025 at 5:34 PM

Err.. .bin file, also once flashed can I re-callibrate the battery indicator and program with Chirp?

REPLY



k_taka

• April 6, 2025 at 4:58 AM

こんにちは、
すべての変更を行い、
CEC0.51HFファームウェアで作業しました。
問題があり350MHzをenableにできません。修正
REPLYします。



huraira

· April 12, 2025 at 6:56 AM

I really hate wearing trends, but rather the more they're near, the almost certain I am to fiddle with them. **Fashions Mag**

REPLY



Emma Watson

· April 20, 2025 at 10:36 PM

Professional write my assignment focus on student success, offering unique content, timely delivery, and academic expertise in a wide range of subjects for university-level excellence.

REPLY



Richard Thomson

• May 11, 2025 at 11:30 PM

Nice to visit your blog. It is full of with relevant knowledge and information. Looks fabulous, You're definitely an inspiration and the way you're always trying new things and sharing your work. I finally found a great post here. I really enjoyed reading this article. Thanks for sharing this valuable information. It's difficult to find high-quality information.

Share some more tips to organize things more better.

[Digital Marketing Company in Mohali](#)

REPLY



Tim David

• May 11, 2025 at 11:36 PM

I found this blog post to be very enlightening! You have a great ability to break down complex topics into easy-to-understand information. The examples and stories you included made it relatable and engaging. I was captivated from start to finish. I'm excited to read more of your insightful posts.

[Mohali Real Estate](#)

REPLY



Tim David

• May 11, 2025 at 11:40 PM

This post is a must-read since it is jam-packed with insightful knowledge

REPLY

and helpful advice.
To make difficult subjects understandable to all readers, the author skillfully breaks them down into manageable chunks. We particularly value the concise guidance and practical examples, which can be implemented right away.
[Digital Marketing Agency in Mohali](#)



Top Rated Blogs in North America

• May 17, 2025 at 3:11 PM

Cool

REPLY



Roselyn Castro

• May 19, 2025 at 8:24 AM

[Laptop Screen Repair in Mumbai](#)
[Laptop Charger Shop in Mumbai](#)
[Laptop Battery Replacement in Mumbai](#)
[Acer Laptop Service Center in Malad](#)
[Lenovo Laptop Service Center in Goregaon](#)
[Laptop Repair in Andheri](#)
[Laptop Repair in Powai](#)
[Laptop Repair in Goregaon](#)
[Laptop Repair in Malad](#)

REPLY



henry

• June 19, 2025 at 9:41 PM

Achieve academic success with our [assignment help singapore](#) . Our dedicated team is here to provide

REPLY with quality support

and guidance for all subjects. Our professional tutors provide tailored support to boost your grades and enhance your learning experience.



Carmel Tailoring

• June 28, 2025 at 3:10 AM

If you're looking to buy a truly nice men's suit, Carmel Tailoring & Fine Clothier is the place to go. They don't just sell suits—they create them around you. Every detail, from the fabric and cut to the lining and buttons, is hand-selected with your style and fit in mind. It's a relaxed, one-on-one experience with expert tailors who actually listen. Whether it's your first suit or you're building a sharp wardrobe, they make sure you leave feeling confident and looking your absolute best.

You can explore more or book a fitting at Carmel Tailoring.

REPLY

To leave a comment, click the button below to sign in with Google.



Popular posts from this blog

Release DVPI Version 1.03 (script update)

July 12, 2021

Release DVPI
Version 1.03 There
have been some
changes to ...

SHARE 115 COMMENTS
READ MORE

Introductio n to UV-K5 HF Fullband receive version 0.41 (Changed from 0.40)

March 11, 2024

Introduction to
UV-K5 HF Fullband
receive Version 0.41
(Changed ...

SHARE 40 COMMENTS

READ MORE



About Me



KD8CEC

VISIT PROFILE

Archive 

Labels 

Report Abuse