## CS800 SERIES FIRMWARE VERSION 3.00.04

\*\*\* NOTE – Firmware update 3.00.04 requires loading the VoicePacket2015-03-23.fv for channel annunciation to operate properly. Use the Load Fixed Voice Data routine under the Tools menu. \*\*\*

Scanning resumes on digital channels after unexpected signal loss
Enhanced Channel Access supported for ECHOTEST returns of same radio ID
Startup channel and Home Zone support
Channel knob disable function
2Tone and MDC improvements – automatic recording, emergency alarm, library file
3 character basic encryption support added
Ignition sense function operates properly for shut down sequence
Long channel alias names no longer hang display during rapid switching
Auto disable of high power setting in cases of radio over-temperature conditions
Reduced volume after firmware and code plug updates

## CPS VERSION 4.00.22

Enhanced Channel Access supported for ECHOTEST returns of same radio ID Startup channel and Home Zone support Channel knob disable function 2Tone and MDC improvements – automatic recording, emergency alarm, library file 3 character basic encryption support added